Part number SPUJ190900 2.0mm-travel Horizontal Type SPUJ Series



Basic information




+ гоом

Changeover timing	Non shorting
Travel	2.0mm
Total travel	3.0mm
Operating force	1.5±1N
Mounting method	PC board
Poles	2
Operation	Latching
Terminal type	Straight
Dimensions (W×D×H)	15.2×7.5×8.8mm


Operating temperature range Rating (max.)/(min.) (Resistive load)		-10°C to +60°C 0.1A 30V DC/50µA 3V DC			
	Insulation resistance	100MΩ min. 500V D	νC		
	Voltage proof	500V AC for 1 minute			
Mechanical performance	Terminal strength	5N for 1 minute			
	Actuator strength	Operating direction	50N		
		Pulling direction	50N		
Durability	Operating life without load	10,000 cycles 40mΩ max.			
	Operating life with load (at max. rated load)	10,000 cycles 40mΩ	I max.		
Environmental performance	Cold	-20°C 96h			
	Dry heat	85°C 96h			
	Damp heat	40°C, 90 to 95%RH 96h			
Minimum order unit(pcs.)	Japan	600			
	Export	3,000			

Dimensions



Open an expandable image in a separate window


Mounting Hole Dimensions



Open an expandable image in a separate window


Viewed from direction A in the dimensions.

Actuator Configuration at Front Edge




Open an expandable image in a separate window

Circuit Diagram



Open an expandable image in a separate window

Products Line of Knob



We recommend the use of adhesive to secure the knob when mounting onto switches.

Packing Specifications

Bulk

11/6/24, 5:57 PM SPUJ190900 Product information | SPUJ Series | Push Switches | Switches | Products Search | Products & Technologies | Alp...

Number of packages (pcs.)				
1 case / Japan	600			
1 case / export packing	3,000			

Export package measurements (mm)

400×270×290

Soldering Conditions

Reference for Dip So	ldering
Items	
Preheating temperature	-
Preheating time	
Dip soldering	
Soldering temperature	260±5°C
Duration of immersion	5±1s
Reference for Hand	Soldering
Soldering temperature	
350±10°C	
Soldering time	
3+1/0s	

Notes are common to this series/models

- 1. This site catalog shows only outline specifications. When using the products, please obtain formal specifications for supply.
- 2. Please place purchase orders per minimum order unit (integer).
- 3. Products other than those listed in the above chart are also available. Please contact us for details.

Cautions

- 1. Appling load to terminals during soldering under certain conditions may cause deformation and electrical property degradation.
- 2. Avoid use of water-soluble soldering flux, since it may corrode the switches.
- 3. Check and conform to soldering requirements under actual mass production conditions.
- 4. When soldering twice, wait until the first soldered portion cools to normal temperature. Continuous heating will deform the external portions, loosen or dislodge terminals, or may deteriorate their electrical characteristics.
- 5. Flux from around and above the PC board should not adhere to the switches.
- 6. After mounting the switches, if you intend to put the board into an oven in order to harden adhesive for other parts, please consult with us.
- 7. Before soldering switches with locking mechanism, release the locks. If they are soldered without releasing the locks, the soldering heat may deform the locking mechanism.
- 8. If you use a through-hole PC board or a PC board thinner or thicker than the recommendation, here may be greater heat stress. Verify the soldering conditions thoroughly before use.

11/6/24, 5:57 PM SPUJ190900 Product information | SPUJ Series | Push Switches | Switches | Products Search | Products & Technologies | Alp...

9. Solder the switches with detent at the detent position. Soldering switches fixed at the center of the detent may deform the detent mechanisms.

10. No cleaning.

11. Protect small and thin switches from external forces in the set mounting process.

- 12. Tighten the mounting screws by applying the specified torque. Tightening with larger torque than the specified one will result in malfunction or breakage of screws.
- 13. The products are designed and manufactured for direct current resistance. Contact us for use of other resistances such as inductive (L) or capacitive (C).
- 14. The switch will be break if you apply a greater stress than that specified. Take great care not to let the switch be subject to greater stress than specified.
- 15. Be sure to release the locks before removing the knobs. Otherwise, the locking mechanism may be deformed.
- 16. Be sure to use the forced travel close to the position of the whole travel as mush as possible.
- 17. Insert these switches to the specified mounting surface and mount them horizontally. If not mounted horizontally, these switches will malfunction.
- 18. Use of the switches in a dusty environment may lead the dusts entering through the openings and cause imperfect contact or malfunction. Take this into account for set design.
- 19. Corrosive gas if generated by peripheral parts of a set, malfunction such as imperfect contact may occur. Thorough investigation shall be required beforehand.
- 20. Storage

Store the products as delivered at normal temperature and humidity, out of direct sunlight and away from corrosive gases. Use them as soon as possible and no later than six months after delivery.

Once the seal is broken, use them as soon as possible.

Measurement and Test Methods

Rotational Torque (Operating Force)

Measures the torque (operating force) necessary to rotate (move) the shaft (lever). Unless otherwise specified, measurement shall be made at ambient temperatures of 5 to 35°C, the shaft rotational speed shall be 60° per second, and the lever traveling speed shall be 20mm per second.

Shaft Wobble

Measures the amount of deflection at the specified position from the reference plane, with the specifiedbending moment, applied perpendicularly to the shaft from directions 180 degrees with respect to each other.

Withstand Voltage

Applies AC voltage to the specified spot for a minute and then checks for arc, burning, dielectric breakdown and other abnormalities. Respective terminals may be tested as a group. The sections described below shall be tested unless otherwise specified. However, if the section concerned is so constructed as to conduct, that particular part shall not be tested.

Insulation Resistance

Applies specified voltage to the specified locations and then measures the insulation resistance with a megger. The locations described below shall be tested unless otherwise specified. However, if the section concerned is so constructed as to conduct, that particular part shall not be tested.

Sections to be Tested for Withstand Voltage and Insulation Resistance

- Between terminal and shaft (lever).
- Between terminal and metal cover (frame).

Shaft (Lever) Strength against Push/Pull Actions

Applies a specified force in the axial direction of the shaft (lever) for 19 seconds and then checks the operating part and other sections for deformation, breakage, operating conditions, etc.