<u>3MTM</u> Combination Wrist Strap/Footwear Tester

Combination Wrist Strap/Footwear Tester

This combination tester will check wrist straps, heel grounders, and ESD shoes. Designed for manufacturing areas, this tester is self-supporting, standalone, and portable. Stainless steel base and test button for durability. The solid metal stand pole bolts to base for strength. An included AC adapter or 9-volt battery provides powers. The tester indicates good resistance, high resistance and low resistance. Connects to wrist strap by banana plug, clip, or 10mm snap. Meets ANSI/ESD S20.20 ESD Control Program requirements.

- Standalone wrist strap and foot grounder/shoe tester.
- AC or battery powered.
- Solid construction.
- Easy to use.
- Multiple connections for wrist straps.
- Assembly instructions included.

Specifications

Wrist Strap

Result	Indication	Range (+/-10%)
High Fail	Red Light	>10 megohms
Pass	Green Light+tone	750k-10meg
Low Fail	Yellow Light	<750k
Footwear	5	
Result	Indication	Range (+/-10%)
<u>Result</u> High Fail	Indication Red Light	
	Red Light	Range (+/-10%) >100 megohms 750k-100meg
High Fail		>100 megohms
High Fail Pass	Red Light Green Light+tone	>100 megohms 750k-100meg

Includes: Control unit, stand pole, base, power adapter, battery, hardware,ground wire, instructions, certificate.

Part Numbers

COMBOTESTER

Wrist Strap/Footwear Tester





See More 3M[™] Test Instruments online:







SR METER

FIELD METER COMBOTESTER WITH DATA LOGGING

SR, HUMIDITY, TEMPERATURE TEST KIT

www.3M.com/static

