

Part number **SRBV141201** 8-positions Low-profile Vertical Type SRBV Series

Standard ?

Basic information



+ ZOOM


Poles	1
Positions	4
Changeover angle	30±3°
Changeover timing	Non shorting
Rotational torque	30±15mN·m
Actuator configuration	Flat
Actuator length	L: 20mm
Dimensions (W×D×H)	16.2×18.5×7.5mm

Specifications

Operating temperature range		-10°C to +85°C		
Rating (max.)/(min.) (Resistive load)		0.3A 16V DC/50µA 3V DC		
Electrical performance	Contact resistance (Initial performance/After lifetime)	50mΩ max./150mΩ max.		
	Insulation resistance	100MΩ min. 100V DC		
	Voltage proof	100V AC for 1 minute		
Mechanical performance	Terminal strength	5N for 1 minute		
	Actuator strength	Rotational direction	0.6N·m	
		Push direction	100N	
	Wobble of actuator (load at the tip of shaft: 1N)	Measuring position from mounting surface	15mm	
		Shaft wobble (max. value)	0.3mm max.	
	Applicable mounting dimension	20mm		
Durability	Operating life without load	10,000 cycles 100mΩ max.		
	Operating life with load (at max. rated load)	10,000 cycles 150mΩ max.		
Environmental performance	Cold	-20°C 96h		
	Dry heat	85°C 96h		
	Damp heat	40°C, 90 to 95%RH 96h		
Minimum order unit(pcs.)	Japan	165		
	Export	330		

Dimensions


Mounting Hole Dimensions



[Open an expandable image in a separate window](#)


Viewed from direction A in the dimensions.

Operation Part Details (a)




[Open an expandable image in a separate window](#)

Circuit Diagram and Dummy Terminals



[Open an expandable image in a separate window](#)

Attached Parts



[Open an expandable image in a separate window](#)

The following parts are included with the product.

Packing Specifications

Tray

Number of packages (pcs.)

1 case / Japan	165
1 case / export packing	330

Export package measurements (mm)

400×270×185

Soldering Conditions

Reference for Dip Soldering

Items

Preheating temperature	-
Preheating time	-

Dip soldering

Soldering temperature	260±5°C
Duration of immersion	10±1s

Reference for Hand Soldering

Soldering temperature

350±10°C

Soldering time

3+1/0s

Notes are common to this series/models

1. This site catalog shows only outline specifications. When using the products, please obtain formal specifications for supply.
2. Please place purchase orders per minimum order unit (integer).
3. Products other than those listed in the above chart are also available. Please contact us for details.
4. This products can be used in vehicles.
Although these products are designed to perform over a wide operating temperature range, please ensure that you receive and read the formal delivery specifications before use.

Cautions

1. Applying load to terminals during soldering under certain conditions may cause deformation and electrical property degradation.
2. Avoid use of water-soluble soldering flux, since it may corrode the switches.
3. Check and conform to soldering requirements under actual mass production conditions.
4. When soldering twice, wait until the first soldered portion cools to normal temperature. Continuous heating will deform the external portions, loosen or dislodge terminals, or may deteriorate their electrical characteristics.
5. Flux from around and above the PC board should not adhere to the switches.
6. After mounting the switches, if you intend to put the board into an oven in order to harden adhesive for other parts, please consult with us.
7. If you use a through-hole PC board or a PC board thinner or thicker than the recommendation, there may be greater heat stress. Verify the soldering conditions thoroughly before use.
8. Solder the switches with detent at the detent position. Soldering switches fixed at the center of the detent may deform the detent mechanisms.
9. No cleaning.
10. Protect small and thin switches from external forces in the set mounting process.
11. Tighten the mounting screws by applying the specified torque. Tightening with larger torque than the specified one will result in malfunction or breakage of screws.
12. Insert these switches to the specified mounting surface and mount them horizontally. If not mounted horizontally, these switches will malfunction.
13. The products are designed and manufactured for direct current resistance. Contact us for use of other resistances such as inductive (L) or capacitive (C).
14. The switch will break if you apply a greater stress than that specified. Take great care not to let the switch be subject to greater stress than specified.
15. Use of the switches in a dusty environment may lead the dusts entering through the openings and cause imperfect contact or malfunction. Take this into account for set design.
16. Corrosive gas if generated by peripheral parts of a set, malfunction such as imperfect contact may occur. Thorough investigation shall be required beforehand.
17. Storage
Store the products as delivered at normal temperature and humidity, out of direct sunlight and away from corrosive gases. Use them as soon as possible and no later than six months after delivery.
Once the seal is broken, use them as soon as possible.

Measurement and Test Methods

Rotational Torque (Operating Force)

Measures the torque (operating force) necessary to rotate (move) the shaft (lever). Unless otherwise specified, measurement shall be made at ambient temperatures of 5 to 35°C, the shaft rotational speed shall be 60° per second, and the lever traveling speed shall be 20mm per second.

Shaft Wobble

Measures the amount of deflection at the specified position from the reference plane, with the specified bending moment, applied perpendicularly to the shaft from directions 180 degrees with respect to each other.

Withstand Voltage

Applies AC voltage to the specified spot for a minute and then checks for arc, burning, dielectric breakdown and other abnormalities. Respective terminals may be tested as a group. The sections described below shall be tested unless otherwise specified. However, if the section concerned is so constructed as to conduct, that particular part shall not be tested.

Insulation Resistance

Applies specified voltage to the specified locations and then measures the insulation resistance with a megger. The locations described below shall be tested unless otherwise specified. However, if the section concerned is so constructed as to conduct, that particular part shall not be tested.

Sections to be Tested for Withstand Voltage and Insulation Resistance

- Between terminal and shaft (lever).
- Between terminal and metal cover (frame).

Shaft (Lever) Strength against Push/Pull Actions

Applies a specified force in the axial direction of the shaft (lever) for 19 seconds and then checks the operating part and other sections for deformation, breakage, operating conditions, etc.